



de Montageanleitung
en Mounting instructions
fr Instructions de montage
sv Monteringsinstruktion
nl Montage-aanwijzing
it Istruzioni di montaggio
fi Asennusohje
es Instrucciones de montaje
da Monteringsvejledning

Differenzdruckfühler
Differential Pressure Sensors
Sonde de pression différentielle
Differenstryckgivare
Drukverschilopnemer
Sonda di pressione differenziale
Paine-eroanturit
Sondas de diferencia de presión
Trykdifferensføler



QBM2030-..
QBM3020-..
QBM3120-..



**QBM2030-..
QBM3020-..**




QBM3120-..




Zero Reset


1.




2.



3.




QBM2030-..





DIP Switch	QBM2030-1U	QBM2030-5	QBM2030-30
	100 Pa	500 Pa	0...3000 Pa
	+/- 100 Pa	250 Pa	0...1500 Pa
	+/- 50 Pa	200 Pa	0...1000 Pa

QBM3x20-..




DIP Switch

QBM3x20-..



For additional information please refer to the following documents on the Internet:



<http://siemens.com/bt/download>

→ search for "QBM2030" or "QBM3020" or "QBM3120"